

2018年2月号安全談話室 添付図

本図は、発行元 AIC h E、および出版社 John Wiley & Sons, Inc. のご厚意により提供を受けたもので、閲覧用のみとし複写・印刷を禁止します。




Figure 10: VSP test results from sample of material collected from Pipe C compared to “normal” residue sample

Title of material: **How a pipe failure resulted in resizing vessel emergency relief stems** (pages 48–56)

Author: Dennis C. Hendershot, Alan G. Keiter, Jim Kacmar, Joseph W. Magee, Paul C. Morton and Warren Duncan

Title of book/journal: **Process Safety Progress** March 2003 Volume 22, Issue 1

Copyright © 2000-2017 by John Wiley & Sons, Inc. or related companies. All rights reserved.